




CRUSHERFAX

BY MELLOTT
COMPANY



Model:	Metso Mobile Screen ST620	Serial No.	73182	Date:	1/17/2014
Engine	CAT 3056E	Serial No.	35604656	Hours:	6132



Machine History

- Purchased New Metso Mobile Screen ST620 Plant – Serial # 73182 – 6/2006
- Installation Date – 6/2006
- Months Owned – 90 thru 1/2014
- Months in Operation – 51 thru 1/2014 or 56%

ST620 Plant Maintenance



Work Description – Engine, Conveyor, Frame, Screen

- Replaced Adjustment Unit on Conveyor – 9/2013
- Replaced Batteries – 5/2012
- Replaced Level Indicator, Rubber Springs, Working Light, Bearings, Tail Pulleys, Rollers, Skirtboard, Key Switch – 10/2011
- Replaced MV3 Vibrator on Screen – 7/2011
- Replaced Shaft and Bearing on Conveyor – 6/2011
- Replaced Fuel Pump, Pulleys, Temperature Sensor on Engine – 3/2011
- Replaced Display Screen – 5/2010
- Replaced Alternator, Conveyor Bearings – 4/2010
- Replaced Rubber Supports, Filters, Temperature Gauge, Bearings, Belt Scrappers – 2/2008



CRUSHERFAX

BY **MELLOTT**
COMPANY



Model: Metso Mobile Screen ST620		Serial No. 73182		Date: 1/7/14	
Engine Model - CAT 3056E		Engine Serial # 35604656		Hours - 6132	
Work Order Directive				Year	Month
Machine Idle				2014	1
Prepared Machine for next job - Machine Idle				2013	11-12
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2013	10
Machine Idle - Replaced Adjustment Unit on Conveyor				2013	1-9
Machine Idle - Replaced Battery				2012	5-12
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2012	4
Machine Idle				2012	1-3
Machine Idle				2011	11-12
Prepared Machine for next job - Machine Idle				2011	10
Replaced Level Indicator, Rubber Springs, Work Lights, Bearings, Tail Pulleys, Rollers, Skirtboard, Key Switch				2011	10
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2011	10
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2011	8
Replaced MV3 Vibrator on Screen				2011	7
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc - Replaced Shaft and Bearing on Conveyor				2011	6
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2011	4
Replaced Fuel Pump, Temperature Sensor				2011	3
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2011	2
Machine Idle				2010	12
Prepared machine for next job - Machine Idle				2010	10
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2010	8
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2010	6
Replaced Display Screen				2010	5
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc - Replaced Alternator, Conveyor Bearings				2010	4
Machine Idle				2010	1-3
Prepared Machine for next job - Machine Idle				2009	11-12
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2009	10
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2009	8
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2009	6
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2009	4
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc - Replaced Rubber Supports, Filters, Temperature Gauge, Bearings, Belt Scrappers				2009	2
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2008	12
Machine Idle				2008	1-11
Machine Idle				2007	7-12
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2007	6
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2007	4
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc				2007	2

Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2006	12
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2006	10
Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2006	8
Machine Installation	2006	6
Purchased Machine	2006	6