




# CRUSHERFAX

BY MELLOTT  
COMPANY



Model: HP300	Serial No. 126697	Date: 3/13/14
--------------	-------------------	---------------

## Machine History

- Purchased New from Metso – 04/2010
- Installation Date – 06/2011
- Months Owned – 48 thru 03/2014
- Months in Operation – 30 thru 03/2014 or 62.5%
- Hours: 1590 – 12/2013


## Frame

- New – 01/2003
- Reconditioned – 06/2011

## HP300 Cone Work




### Work Description – HP300 Cone Serial # 126697

- New Tramp Release Cylinder – 8/2013
- New Lube Pump and Motor – 7/2013



# CRUSHERFAX

BY MELLOTT  
COMPANY



Model: Metso HP300 Cone Crusher		Serial No. 126697	Date: 3/13/2014	
Object ID	Object Description	Work Order Directive	Date	Month
HP300-002	Crusher,Cone,HP300,Metso			
		Machine Idle at Facility	2014	1-3
		Machine Idle at Facility	2013	12
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2013	10
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2013	8
		Installed New Tramp Release Cylinder	2013	8
		New Lube Pump and Motor installed	2013	7
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2013	6
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2013	4
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2013	2
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2013	2
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2012	12
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2012	10
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2012	8
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2012	6
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2012	4
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2012	2
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2011	12
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2011	10
		Minor On Site Repairs - oil changes, plant Servicing, clean up, etc	2011	8
		Installation at Crushing Site	2011	7
		Cone Idle	2011	1-6
		Cone Idle	2010	4-12
		Purchased HP300 Cone	2010	4